How do I create Quality Sample?

- Go to Quality --> Quality Sample.
 Click on New.
- 3. Quality Sample editor screen is opened.

| Sample Detail | | | | | | | | Ad | Additional Attributes | | | | |
|-------------------|---------------------|-------------|-------------|--------------------------------------|----------------------------|-----------------|--------|-----------------|-----------------------|---------------------|-------------|-------|-----|
| Sample Type | | | | ✓ Origin: | | | | ~ | 88 | Layout Q, Filter Re | ecords (F3) | | |
| Sample Number: | | | | Sample Qty: | | | | ~ | | Attribute | Attribute | Value | Rei |
| Contract Number: | | | | Representing | g Qty: | | | ~ | | | | | |
| Shipment Number: | | | | Sample Note | | | | | | | | | |
| Container Number: | | | | Sample State | atus: | Received | | | | | | | |
| Item No: | | | | Description: | N | | | | | | | | |
| Party Name: | | | | ✓ Testing Start | Date: | 01/28/2016 | | 1 | | | | | |
| Reference No: | | | | Testing End | Testing End Date: | 01/28/2016 | | | | | | | |
| Lot No: | | | Received Da | te: | 01/28/2016 | | 12 | | | | | | |
| Lot ID: | | | | Sampling En | pling End Date: 01/28/2016 | | | | | | | | |
| Lot Status: | | | | Sampling Method: | | | | | | | | | |
| Test Detail | | | | | | | | | | | | | |
| B Layout Q | Filter Records (F3) | | | | | | | | | | | | |
| Test Name | Property Name | Description | Min Value | Max Value | Actu | Value Mandatory | Result | Accepted Values | Com | iment | | | |

8. Fill all the Test Detail.

| 1 | est Detail | | | | | | | | | | |
|---|-------------------|-------------------|---------------|-----------|-----------|--------------|-----------|--------|-----------------|---------|---|
| B | B Layout Q Fi | lter Records (F3) | | | | | | | | | |
| | Test Name | Property Name | Description | Min Value | Max Value | Actual Value | Mandatory | Result | Accepted Values | Comment | |
| | Ash Content | HM Cadmium | HM Cadmium | 0 | 1 | | No | | | | - |
| | Ash Content | HM Ferrous Ma | HM Ferrous Ma | 0 | 0.005 | | No | | | | |
| | Ash Content | HM Lead | HM Lead | 0 | 3 | | No | | | | |
| | Brew Test | Brew Test | Brew Test | 10 | 20 | | No | | | | |
| | Caffeine Analysis | HM Cadmium | HM Cadmium | 0 | 1 | | No | | | | ٣ |
| | | | | | | | | | | | |

- 9. Click on Save.
 10. Click on Approve / Reject